Technical Service Bulletin

K2 BIKE 19215 Vashon Highway SW Vashon, Washington 98070-5236 USA
P: 206-463-3631 x1345 F: 206-463-8830
E: eddie_rea@K2Sports.com

Bulletin: **TSB-112202** **Date:** **11/22/02**

Subject: **03 Zed 3.0 & Attack 3.0 Crank Adjustment**

Background:

It has been discovered that there is an isolated front shifting issue on some of the 2003 Zed 3.0 & Attack 3.0 bicycles. When indexed to the middle ring and largest cog in the rear, the chain will "auto shift" to the small chainring. This is due to insufficient torque applied to the crank bolt during the initial assembly at the factory.

Fix:

Remove the Truvativ crank from the spindle and re-install to a torque value of 35 ft/lbs. This will drive the crank to the proper depth on the bottom bracket spindle.

Eddie Rea
Technical Services
P: (206) 463 3631 x1345
F: (206) 463 8830
E: eddie_rea@k2sports.com

K2 Bike is a world
Leader in the design,
Marketing and sales of high quality
bikes and accessories for Road, Mountain and BMX use.