Bar will not work on the following stems: clamping area on these stems exceed the recommended bar clamping area of 58 mm

Direct Mount Stems

- Answer DH: 62mm Clamp Width
- Answer DH-One: 62mm Clamp Width
- Renthal Integra: 64mm Clamp Width
- Thomson Direct Mount: 65mm Clamp Width
- Deity Locust DM: 65mm Clamp Width

Standard Steer Tube Mount Stems

- Answer Rove DJ Stem: 61mm Clamp Width