
05/18/04


TECHNICAL BULLETIN

Mounting Bolts for Manitou Direct Mount Disc Brake

Hayes Brakes has updated the mounting bolt standard for 2004, this affects bikes with post mount or Manitou type forks. With repeated removal or adjustment of the brake caliper the threaded post on the fork leg can become worn or damaged. The new standard is an increase in the total length of the mounting bolt. The longer bolt will reduce wear and tear on the threaded post of the fork leg. For this reason we ask that you replace the affected models with the new hardware provided by Hayes and follow the torque spec as indicated. To have new hardware sent to you at no cost contact ***Hayes Disc Brake at 1-888-686-3472. www.hayesdiscbrake.com***



TORQUE MOUNT BOLTS TO
80 + OR - 5 IN-LBS.



K2 BIKE 19215 VASHON HWY SW VASHON WA 98070
1-800-225-4119