
06/07/04

TECHNICAL BULLETIN

Ritchey rim and hub issues



It has been brought to our attention that bicycles equipped with Ritchey brand rims and hubs may have one of the following off-quality issues:

Freehub body blowout:
Pawls become stuck or broken and have no engagement.

Wheel build:
Seams stick out, wheel out of round, and varying wall thickness.

ERD to large:
Tire is hard to remove and replace.

If you encounter any of these please contact Kendall at Ritchey USA 650-368-4018 ext...6706. Ritchey is aware of these issues and can drop ship freehub bodys and compelete wheels in advance for a quick resolution to any of the above.
www.ritcheylogic.com

POSSIBLY AFFECTED 2004 MODELS;

ZED 2.0	ATTACK 1.0	MACH S	ENEMY
ZED 3.0	ATTACK 2.0	MACH 1.0	
ZED 4.0		MACH 2.0	
		MACH 3.0	

K2 BIKE 19215 VASHON HWY SW VASHON WA 98070
1-800-225-4119